


MHHS Design Release Note Interim Release.03 Release Date: 02-08-2023



Document owner Design Team Status: Final Document number DEL1275 Date 31/07/2023

Version V1.0 Classification Public



1 Contents

| 1 Contents | 1 |
|------------------------|---|
| 1.1 Change Record | 2 |
| 1.2 Reviewers | 2 |
| 2 INTRODUCTION | 3 |
| 3 OVERVIEW | 3 |
| 3.1 Release Feedback | 3 |
| 4 Impacted Artefacts | 4 |
| 5 Resolved Issues | 5 |
| 6 Unaffected Artefacts | 7 |
| 7 Issues/Limitations | 9 |
| 8 Past Releases | 9 |

1.1 Change Record

| Date | Author | Version | Change Detail | |
|------------|------------|---------|---------------|--|
| 24/07/2023 | Rob Topley | 0.1 | Initial Draft | |
| 31/07/2023 | Rob Topley | 1.0 | Final | |
| | | | | |

1.2 Reviewers

| Reviewer | Role |
|----------|------|
| | |
| | |

2 INTRODUCTION

These are the release notes for Interim Release 3 of the MHHS Design.

Use Release Notes to keep up with what's going on. Release notes provide a summary of what's new and what issues have been resolved within the design.

3 OVERVIEW

Here's what's new or updated within Interim Release 3

Improvements:

- CR15 (DIN243) for Off Peak Solution is included in this release
- DES138 Data Interface catalogue remains the most change impacted artefact for various interfaces and the validation rules

Fixes:

• A number of corrections have been applied for various process models, descriptions and requirements details

Further guidance on the Release.

Versioning:

Interim Releases are NOT a blanket updating of all the design artefacts and models to the next release number. Each Document artefact is separately version controlled and tracked. Interim releases are a collection of updated artefacts which are updated. The version number depends on the last revision of the artefact. Thus, an interim release will publish and consists of documents at different version numbers. Some documents contain multiple models, interfaces, or report definitions which each have a version number. The artefacts' own document version number may contain different objects at different version numbers depending on the changes made to the artefact.

Versions of design artefacts with tracked changes is available on the Red-Lined Design Artefacts page.

Design Models:

Design Models available on the collaboration are also updated in line with the published artefact models within the release. Design models now support relationship with requirements allowing users to drill from process through to requirements.

JSON/YAML:

JSON and YAML files published for V1.3 are in line with the latest version of the DES138 Data interface catalogue, these files will continue to be aligned with future releases.

3.1 Release Feedback

Any queries or feedback on this release or the contents of this release note please contact us via Design@MHHSprogramme.co.uk

4 Impacted Artefacts

The following table contains a list and versions of design artefacts/documents which have been updated.

| Artefact | Version Number | Theme | Impact |
|--|-------------------|---|--|
| E2E001 – End-to-End Solution Architecture | V3.3 | Supporting Documents | Additional Solution Design Details |
| MHHSP - ERI011A – ECS Reports - Internal | V5.2 | Supporting Documents | Data Correction |
| MHHSP - ERI011B – ECS Reports - External | V5.2 | Supporting Documents | Data Correction |
| MHHSP_EDI021_ISD_Entities | V5.2 | Supporting Documents | Data Correction |
| MHHSP-BP003-Change of Service - Data Service | V5.3 | MPAN Ownership | Process Correction |
| MHHSP-BP004-Data Collection | V5.1 | MPAN Ownership | Process Correction |
| MHHSP-BP008-Change of Energisation | V5.1 | Metering Changes | Process Correction |
| MHHSP-BP009-ChangeofMeter | V5.2 | Metering Changes | Process Correction |
| MHHSP-BP010-Change of Registration Data | V5.2 | Metering Changes | Process Correction |
| MHHSP-BP011-Change of ConType andor Mkt Segment | V5.3 | Metering Changes | Process Correction |
| MHHSP-BPD009 – Change of Metering | V5.1 | Business Process Description | Process Correction |
| MHHSP-BRS001-Data Service Requirements | V5.3 | Supporting Documents | Requirement Correction |
| MHHSP-BRS002-Metering Service requirements | V5.2 | Supporting Documents | Requirement Correction |
| MHHSP-BRS003-Registration Service requirements | V5.2 | Supporting Documents | Requirement Correction |
| MHHSP-BRS004-Supplier Overview | V5.1 | Supporting Documents | Requirement Correction |
| MHHSP-BRS005-LDSO Overview | V5.2 | Supporting Documents | Requirement Correction |
| DES138-Interface Catalogue | V5.3.2 | Meter to Bank, Metering Changes, MPAN Ownership | Interface corrections |
| DES229-IF005_UseCaseGuide | V1.3 | Supporting Documents | IF005 corrections |
| MHHSP-METH001_SDS_Validation_Estimation | V5.2 | Supporting Documents | Statement Correction |

| MHHSP_OPC001_Operational_Choreography | V5.2.6 | Supporting Documents | Statement correction |
|---|--------|----------------------|-----------------------------------|
| JSON/YAML files | V1.3 | Supporting Documents | Updated Swagger definitions |
| MHHS-DEL964 BPM-003 - Change of Service - Data Service - Forward Migration | V1.3 | Migration Design | Process correction |

5 Resolved Issues

All fixes Design Issue Notifications (DINs) and the Request for Change (RFCs) to MHHS Design since the last release that have been resolved in this release are included in the list below:

| DIN/RFC Ref | Description | Status |
|--------------|--|--------|
| MHHS-DIN-17 | MAP History availability to Metering Service | Fixed |
| MHHS-DIN-70 | Addition of MDR validation rule | |
| MHHS-DIN-87 | Process clarification for meter removal and de-energisation on same job | Fixed |
| MHHS-DIN-94 | IF-005 rejections | Fixed |
| MHHS-DIN-107 | Update to definition of DI-301 LLF ID in the ESC Reporting Data Catalogue | Fixed |
| MHHS-DIN-154 | IF-019 validation gap on primary and subsidiary MPAN | Fixed |
| MHHS-DIN-243 | CR-015 E7/E10 Off Peak Consumption Solution | Fixed |
| MHHS-DIN-321 | B005 add to IF-036 | Fixed |
| MHHS-DIN-372 | Mapping Roles | Fixed |
| MHHS-DIN-383 | Change of Segment Scenario | Fixed |
| MHHS-DIN-384 | IF-038 and IF-039 blocks not the same | Fixed |
| MHHS-DIN-391 | IF-019 validation gap on principal and subsidiary MPAN | Fixed |
| MHHS-DIN-395 | Obfuscation of Connection Type Indicator in IF-021 | Fixed |
| MHHS-DIN-396 | Update IF-019 REG1001 to only apply to Create and Add event codes | Fixed |
| MHHS-DIN-416 | MIG-001 New App Scenario Code MCS (Migration Change of Supplier) | Fixed |
| MHHS-DIN-417 | MIG-002 Validation Rules for Scenario MCS (Migration Change of Supplier) | Fixed |
| MHHS-DIN-418 | MIG-003 New App Scenario Code MCA (Migration Change of Agent [Service Provider]) | Fixed |
| MHHS-DIN-419 | MIG-004 Validation Rules for Scenario MCA (Migration Change of Agent [Service Provider]) | Fixed |
| MHHS-DIN-420 | MIG-005 - IF-31 Check valid MHHS Supplier | Fixed |
| MHHS-DIN-421 | MIG-006 - Prevent use of Migration Scenario IDs | Fixed |
| MHHS-DIN-422 | MIG-007 Connection Type/Segment not yet Populated | Fixed |
| MHHS-DIN-423 | MIG-008 Auto Realign Functionality | Fixed |
| MHHS-DIN-424 | MPRS access to correlation ID | |

| MHHS-DIN-430 | MIG-12 New Val Rule for IF-019 | Fixed |
|--------------|---|-------|
| MHHS-DIN-433 | MIG-015 Switch in Progress Mig Rejection | Fixed |
| MHHS-DIN-434 | MIG-016 New IF-003 | Fixed |
| MHHS-DIN-437 | MIG-019 IF-005 Validation Rule | Fixed |
| MHHS-DIN-438 | MIG-020 REGS Design Clarification | Fixed |
| MHHS-DIN-439 | MIG-021 No Supplier Updates during Rev MIgration (IF-025) | Fixed |
| MHHS-DIN-440 | MIG-022 No CDCs Updates during Rev MIgration (IF-038) | Fixed |
| MHHS-DIN-445 | Spec of IF-024 in DES138 Interface Catalogue | Fixed |
| MHHS-DIN-447 | Conditional Mandatory not applied in Swagger correctly | Fixed |
| MHHS-DIN-448 | Mandatory fields not applied correctly in S1 block | Fixed |
| MHHS-DIN-449 | Change to IF-037 | Fixed |
| MHHS-DIN-450 | Change to IF-005 Validation Rules | Fixed |
| MHHS-DIN-452 | Refine Consent Checking Rules on IF-031 | Fixed |
| MHHS-DIN-453 | Issuing of IF-020's | Fixed |
| MHHS-DIN-454 | Update to ISD M7 | Fixed |
| MHHS-DIN-455 | Update Op Choreography (Event Move from IF-013 to IF-014) | Fixed |
| MHHS-DIN-456 | Swagger Correction - DI-844 | Fixed |
| MHHS-DIN-458 | New IF-019 Related MPAN Validation Rule | Fixed |
| MHHS-DIN-460 | PIF-019 structure & Principle -> Principal | Fixed |
| MHHS-DIN-461 | Misalignment between DES-138 and Swagger for DIP Connection Provider ID | Fixed |
| MHHS-DIN-462 | Schema Optionality incorrectly defined for some Interfaces | Fixed |
| MHHS-DIN-463 | No ability de-register from receiving Status messages in Swagger | Fixed |
| MHHS-DIN-464 | Clarity required on values expected for /dip-channel/{id} for submitEvents on Swagger | Fixed |
| MHHS-DIN-465 | Update to BP010 - Related MPANs | Fixed |
| MHHS-DIN-466 | Change of MPAN Status during Service Provider Appointment Process. | Fixed |
| MHHS-DIN-468 | Routing of IF-020 | Fixed |
| MHHS-DIN-469 | Removal of Z0 & Z1 data items in ERI011B - ECS Reports External | Fixed |
| MHHS-DIN-470 | Clarity on nullable fields | Fixed |
| MHHS-DIN-471 | Update to REP-003 in ERI011B - ECS Reports External | Fixed |
| MHHS-DIN-473 | Definition of Network Operations | Fixed |
| MHHS-DIN-476 | Inconsistency between enum fields and nullable definition | Fixed |
| MHHS-DIN-479 | Change to Consent Notification on IF-036 | Fixed |
| MHHS-DIN-480 | Reverse DIN-105 | Fixed |
| MHHS-DIN-495 | Correction to BPM003 | Fixed |

Refer to published DIN log for further information on DINs listed.

6 Unaffected Artefacts

The following table contains a list and latest version of design artefacts/documents which are under change control and have NOT been updated in this release.

| Ref | Artefact | Version Number |
|---------------|---|-------------------|
| MHHSP-BP001 | Change of Supplier | 5.00 |
| MHHSP-BP002 | Change of Service- Metering Service | 5.2 |
| MHHSP-BP003A | CSS and DCC Update | 5.00 |
| MHHSP-BP003B | Change of Existing Service Appointment Details | 5.00 |
| MHHSP-BP003C | Transfer of Reads - Change of Data Service | 5.1 |
| MHHSP-BP005 | Data Processing | 5.1 |
| MHHSP-BP007 | Disconnection | 5.2 |
| MHHSP-BP013 | Demand Disconnection Events | 5.00 |
| MHHSP-BP016 | Consumption Amendment | 5.00 |
| MHHSP - BP018 | Load Shaping Service (ECS) | 5.00 |
| MHHSP - BP019 | Market-wide Data Service (ECS) | 5.00 |
| MHHSP - BP020 | Volume Allocation Service (ECS) | 5.1 |
| MHHSP-BP021 | Industry Standing Data (ECS) | 5.00 |
| MHHSP-BPD001 | Change of Supplier | 5.00 |
| MHHSP-BPD002 | Change Of Metering Service | 5.2 |
| MHHSP-BPD003 | Change Of Data Service | 5.1 |
| MHHSP-BPD003A | CSS and DCC updates | 5.00 |
| MHHSP-BPD003B | Change of Existing Service Appointment Details | 5.00 |
| MHHSP-BPD003C | Transfer of Reads COS_CODS | 5.1 |
| MHHSP-BPD004 | Data Collection | 5.00 |
| MHHSP-BPD005 | Data Processing | 5.00 |
| MHHSP-BPD007 | Disconnection | 5.2 |
| MHHSP-BPD008 | Change of Energisation Status | 5.00 |
| MHHSP-BPD010 | Change of Registration Data | 5.1.1 |
| MHHSP-BPD011 | Change of Con Type or Market Segment | 5.1 |
| MHHSP-BPD013 | Demand Disconnection Events | 5.00 |
| MHHSP-BPD016 | Consumption Amendment | 5.00 |
| MHHSP-BPD018 | Load Shaping Service (ECS) | 5.00 |
| MHHSP-BPD019 | Market-wide Data Service (ECS) | 5.00 |
| MHHSP-BPD020 | Volume Allocation Service Business Process Descriptions | 5.1.1 |
| MHHSP-BPD021 | Industry Standing Data (ECS) | 5.00 |
| | | |

| MHHSP-BRS006 | EES & SDEP Requirements | 5.00 |
|-----------------------------|--|------|
| MHHSP-BRS007 | Load Shaping Service Requirements (ECS) | 5.00 |
| MHHSP-BRS008 | Market-wide Data Service Requirements (ECS) | 5.00 |
| MHHSP-BRS009 | Volume Allocation Service Requirements (ECS) | 5.00 |
| MHHSP-BRS010 | Industry Standing Data Requirements (ECS) | 5.00 |
| MHHSP-BRS012 | Annual Consumption Requirements | 5.00 |
| MHHSP-BRS013 | Demand Disconnection Events Requirements (ECS) | 5.00 |
| MHHSP-BRS014 | ECS Registration Data Archive Requirements | 5.00 |
| MHHSP-METH002 | ADS_Validation_Estimation | 5.1 |
| MHHSP-METH004 | UMSDS_EM_Functions | 5.1 |
| MHHSP-METH005 | LSS Method Statement | 5.00 |
| MHHSP-METH006 | VAS Method Statement | 5.00 |
| MHHSP-METH007 | MDS Method Statement | 5.00 |
| MHHSP-METH008 | DDE Method Statement | 5.00 |
| MHHSP-METH009 | UMSO_Method_Statement | 5.1 |
| MHHSP-METH010 | Annual Consumption | 5.00 |
| MHHSP-EM021 | ISD Entity Map | 5.00 |
| MHHSP-DES052 | Logical Data Model | 5.00 |
| MHHSP-DES203 | Traceabiility Matrix | 5.1 |
| MHHS-E2E002 | End to End Non Functional Requirements | 3.01 |
| MHHSP-DIP001 | DIP Functional Specification | 2.20 |
| MHHS-DEL396 MHHSP-DIP002 | DIP Non Functional Requirements | 2.30 |
| MHHSP-DIP-003 | End to End Security Architecture | 1.20 |
| MHHSP-DIP-004 | Cyber Security Connection Guidance | 3.00 |
| MHHSP-DIP-005 | End to End Security Requirements | 1.4 |
| MHHSP-DIP-005 | End to End Security Requirements - excel version | 1.4 |
| MHHS-DIP094 | Interface Code of Connection - DRAFT word document | 0.2 |
| MHHS-FFIEC- Cyber- | | |
| Assessment-Tool | Cyber risk assessment - Excel spreadsheet | 3.4 |
| MHHS-DES001a | Functional Specification - Transaction Volumes - Appendix A | 0.20 |
| MHHSP-DES196 | D-flow and Interface Mapping | 0.3 |
| MHHS-DEL960 | Migration Design Document | 1.0 |
| MHHS-DEL973 | Migration Design Requirements Log | 1.0 |
| MHHS-DEL962 | BPM-001 - Change Of Supply - Forward Migration | 1.0 |
| MHHS-DEL963 | BPM-002 - Change of Service - Metering Service - Forward Migration | 1.2 |

| MHHS-DEL968 | BPD001 - Change of Supply (Forward Migration) | 1.0 |
|-------------|--|-----|
| | BPD002 - Change of Service - Metering Service (Forward | |
| MHHS-DEL969 | Migration) | 1.2 |
| | BPD003 - Change of Service - Data Service (Forward | |
| MHHS-DEL970 | Migration) | 1.1 |
| MHHS-DEL965 | BPM-001 - Change Of Supply - Reverse Migration | 1.0 |
| | BPM-002 - Change of Service - Metering Service - Reverse | |
| MHHS-DEL966 | Migration | 1.0 |
| | BPM-003 - Change of Service - Data Service - Reverse | |
| MHHS-DEL967 | Migration | 1.0 |
| MHHS-DEL971 | BPD001 - Change Of Supply - Reverse Migration | 1.0 |
| MHHS-DEL972 | BPD002 - Change Of Metering Service - Reverse Migration | 1.0 |
| MHHS-DEL973 | BPD003 - Change Of Data Service - Reverse Migration | 1.0 |
| | | |

7 Issues/Limitations

This section describes any known limitations and obstacles to the release and fixes implemented.

Certain artefacts cannot be change marked. Reference will be made to documents which identify where these changes exist within the artefacts. Artefact documents in PDF form will be issued with tracked changes on to highlight where the changes are in the document.

Certain artefacts do not include a version/change history record, change history section have been added in some cases and changes are tagged using comments to provide a reference of DIN changes made to the artefact. Within Excel while all changes are marked, not every cell is tagged with the DIN reference as it was not possible to tag groups of cells with a DIN ref.

Transition Design documents are not currently under design release, change and configuration control at this time.

8 Past Releases

Details of previous release please refer to the relevant release note for details:

| Version Number | Release Date | Release type |
|----------------|--------------|-------------------|
| 5.0 | 21/02/2023 | Baseline |
| 5.1* | 14/06/2023 | Interim Release 1 |
| 5.2* | 05/07/2023 | Interim Release 2 |

* Various version numbering occurs on different documents for each release for details see previous release notes.